


ACCESORIOS PARA CALENTADORES DE INMERSION ROSCADOS




JUNTAS

Kligerit
Inox

ROSCA M 45 x 200	
Dim. mm	Referencia
Ø45	MP 397790
Ø45	MP 395720

ROSCA 1 1/2" G	
Diim. mm	Referencia
Ø48	MP 397890

ROSCA M 77 x 200	
Dim. mm	Referencia
Ø77	MP 398190
Ø77	MP 395820



TUERCAS

Latón
Acero

E/P=60	MP 155060
E/P=60	MP 155020

E/P=60	MP 160060
--------	-----------

E/P=90	MP 157060
E/P=90	MP 157020




BRIDA PARA SOLDAR

Acero
Inox

MP 165000
MP 165020

MP170000

MP 167000
MP 167020




TAPON CIEGO

Latón
Acero
Inox

E/P=60	MP 131760
E/P=60	MP 131600
E/P=60	MP 131620

E/P=60	MP 145760
E/P=60	MP 145720

E/P=90	MP 135660
E/P=90	MP 135600
E/P=90	MP 135620




TAPON PROTECTOR DE ALUMINIO

H x Ø
PE

100x65	40045 A
Nº 11 o 13	

100x65	40045 A
Nº 11 o 13	

125x100	40070 A
N° 16	




CAJA DE BORNES ORIENTABLE DE ALUMINIO

$$A \times A$$

90x90	ORPM 45 PE13
80	ORPM 45 PE16

90x90	ORPM 45 PE13
80	ORPM 45 PE16

110x110	ORGM 77 PE 16
105	ORGM 77 PE 21
	ORGM 77 PE 29



CAJA DE BORNRS EN CHAPA DE ACERO

$$A \times B$$

165x20	ORS 35 PE13
75	ORS 45 PE13+11

165x20	ORS PE13
75	ORS PE13+11

165x20	ORS 77 PE16
75	ORS 77 PE21
	ORS 77 PE16+11
	ORS 77 PE21+11